# Navajo Abandoned Uranium Mine

## Site Screen Report

This form is for use at the site of abandoned uranium mines (AUM) located on Navajo Nation lands. Applicable sites include all mine and mine features that have or have not undergone reclamation by the Navajo Abandoned Mine Lands Reclamation Program, including features, adits, pits and waste piles. Applicable sites also include all AUM sites listed in the USEPA CERCLIS database, all sites listed in the 2008 AUM GIS Report issued by USACOE and USEPA, all AUM sites on allotment lands associated with the Navajo Nation, and any and all AUM sites not listed in any database located on Navajo lands. Reconnaissance of any sites located on lands adjacent to Navajo lands that may be impacting Navajo lands will need to be coordinated with the authorities appropriate to those lands.

The purpose of the form is to ascertain the status and location of the identified AUM site, and record all immediate site information associated with the mine site. Decisions and recommendations on what additional steps are needed will be provided on a separate document.

## **Cottonwood Butte AUM Site**

Navajo AUM Northern Region

Prepared by:

Weston Solutions, Inc.

Contract: W91238-06-F-0083

12767.063.496.1111

March 2010

Part I	Site Identification, Location and Status		
Site Names and ID numbers as applicable			
Mine ID:	28		
Map ID:	N129		
CERCLIS:	NNN000908835		
Navajo Abandoned Mine Land Reclamation Program: NA-0411			
Local name / Aliases: Plot 8; VCA Plot 8; East Reservation Lease Plot 8			
Chapter and local area: Red Valley Chapter			
County: San	Juan State: New Mexico		
<b>Lat/Long:</b> 36.772056073 N / -109.040215832 W			
Nearby road and highway: Indian Route 63 Local Post Office: Beclabito, NM			
Surface Land Status: check one or more and provide ownership and contact information below			
Tribal Trust I Private Bureau of Lat State	Tribal Fee Land		
Subsurface Mineral Rights:			
The mineral rights ownership was identified as Indian.			
Claim and operator information:			
The mine site surface land status is classified as Tribal Trust Land. Historical documents showed the operator of the mine as Vanadium Corp. of America in 1949 and 1954, and Alfred Nelson from 1950 to 1951. No other historical ownership / lease information was identified in the EPA/AUM database.			
Number of residential structures within 200 feet of mine:			
None			
Estimated volume of mine waste onsite:			

None

### Part II Summary of radiological readings

### **Highest gamma radiation measurement:**

78,200 counts per minute (cpm)

#### **Describe any other radiological measurements:**

A total of 4,859 gamma radiation measurements were collected from the mine site, ranging from 5,552 cpm to 78,200 cpm. Measurements in the vicinity of the reclamation cap were found at levels above 65,000 cpm. The measurements are represented in Figures 1 and 2.


#### **Background Locations**

**Average background** = 7,420 cpm

#1 7,546 cpm #2 7,294 cpm

#### **Distribution Chart and Statistics:**

The following chart and statistics were generated by ESRI ArcGIS 9.3.1, and show the general distribution of the site gamma radiation measurements. The horizontal X axis represents the gamma radiation reading levels in cpm (lowest levels to the left). The vertical Y axis represents the frequency of each gamma radiation level.



 Count:
 4859

 Minimum:
 5520,00000

 Maximum:
 78200,00000

 Sum:
 67177535,00000

 Mean:
 13825,38279

 Median:
 10344,00000

 Standard Deviation:
 9260,93429

#### Part III Status of Reclamation and Mine Waste

The following information was obtained from the Navajo Abandoned Mine Land Reclamation Program (NAMLRP) Point Features Database:

NAMLRP Status of the mine site: Reclaimed: Yes Waste Pile onsite: No

**NAMLRP Project Number:** NA-0411

**NAMLRP Mine features:** 1 Portal, 1 Rim Strip / Pit

The following information was obtained from field observations collected during the 2009 site screening:

Provide description and status of all mine sites and features at site. Include all waste piles, adits, pits and other features, and indicate whether they are open, closed, covered, capped, buried or unreclaimed. Indicate approximate size, shape and extent, including description of any reclamation caps. Note condition of all caps.

#### Observed reclamation work and status:

#### **Adits**

Sealed adit with stacked stone monument

#### **Waste Piles**

None

## **Pits**

None

#### **Shafts**

None

#### **Other Debris and Mine Features**

Possible reclamation cap, 20' x 60', red clay mixed with waste rock

#### **Part IV**

#### **Site observations and Environs**

Observed Structures: list number of and describe human habitation status of structures at the following distances from mine:

**0 to 200 feet:** None

200 feet to 0.25 mile: None

Observed Public or commercial structure: list and describe all schools, clinics, Chapter Houses, places of business and any other structure used by members of the community at the following distances:

0 to 200 feet: None

200 feet to 0.25 mile: None

Levels measured around the perimeter(s) of the identified structure(s):

None

Observed water sources: list the number and type of wells and surface water sources that are potentially used for human consumption at the following distances from the mine:

0 to 0.25 miles: None

**0.25 miles to 4 miles:** Livestock well approximately 0.3 miles east of site

Sensitive environments: note and describe all sensitive environments located within visible range of the mine site, including: wetlands, endangered species, habitats and approximate locations of sites that may be under protection of the government of the Navajo Nation.

None observed

Known Site History: include information from interviews with Chapter officials and residents. Note information on mine ownership, type of mining operation, period of operation, known amount of production, and any other information as provided.

Cottonwood Butte mine consists of an area of 9,923.02 m<sup>2</sup>. The mine was identified as being operational from 1950 to 1954. Historical documents showed the operator of the mine as Vanadium Corp. of America in 1949 and 1954, and Alfred Nelson from 1950 to 1951. While operational, the mine had a total reported production volume of 250 tons. No other historical information or any additional ownership / lease information was identified in the EPA/AUM database.

## Part V Response Action Summary

**Site Name(s):** Cottonwood Butte **Chapter:** Red Valley

## **Decision Criteria**

Is there an unreclaimed waste pile at the site? No

At what distance from the waste pile is the nearest residential structure located? None

At what distances from the waste pile are there potential drinking water sources? None

Is there a reclamation cap or sealed adit in place at the site? Yes

Is the cap/seal functionally intact? Yes

Is the cap/seal sufficiently degraded to create a concern about releases? No

At what distance from the cap/seal is the nearest domestic structure located? 0.5 mi

At what distance from the cap/seal is the nearest domestic drinking water source? 0.3 mi

#### **Summary of emergency response factors**

None

## **Summary hazard ranking system factors**

None

#### **Summary of reclamation factors**

1 sealed adit; 1 possible reclamation cap

## Part VI Photos



Photo 1. Livestock well approximately 0.3 miles east of mine site



Photo 2. Livestock well approximately 0.3 miles east of mine site




Photo 3. Mine site down slope area




Photo 4. Stacked rock marking adit location



Photo 5. Clay reclamation cap



Photo 6. Housing compound approximately 0.5 miles from site



Photo 7. Housing compound approximately 0.5 miles from site


Name:

# Part VII Contacts Reports and Information

Stanley Edison (928) 871-6861

Eugene Esplain (928) 871-7331			
Title or official role (if any) Navajo EPA Superfund Program			
Address PO Box 2946, Window Rock, AZ 86515			
Information provided <u>Lead Regulatory Agency</u>			
Name			
Title or official role (if any)			
Address			
Telephone number			
Information provided			
Name			
Title or official role (if any)	_		
Telephone number			
Information provided			
Name			
Title or official role (if any)	_		
Telephone number			
Information provided			

Figure 1 - Gamma Radiation Measurements, Above Two Times Background **Cottonwood Butte Mine (28)** Red Valley Chapter, Navajo Nation, Arizona



- < 2X Backgound
- > 2X Background

Gamma survey conducted 10/2009 Measured as counts per minute (cpm)

Average background = 7,420 cpm




Inaccessible due to steep grades

**General Direction Down-Slope Mine Claim Boundaries** 



Figure 2 - Gamma Radiation Measurements **Cottowood Butte Mine (28)** Red Valley Chapter, Navajo Nation, Arizona



## Legend

**Gamma Radiation Measurements** 

- 0 10,000
- 10,000 15,000
- 15,000 20,000
- 20,000 50,000
- 50,000 100,000
- > 100,000



**Observed Waste Pile** 



**Observed Adit** 



Inaccessible due to steep grades



**General Direction Down-Slope** 



**Mine Claim Boundaries** 

Gamma survey conducted 10/2009 Measured as counts per minute (cpm)

Average background = 7,420 cpm

